



Позиция	Количество	Номер для заказа	Описание	PG
1	1	343441310	soft grip	29
2	1	316092700	Gear housing compl.	31
3	1	315107570	Intermediate flange	34
4	1	341604910	spindle	38
5	1	341211380	Drive shaft	37
6	1	341165630	Gear	38
7	1	143114790	RI.KU.LA. 6X 19X 6	15
8	1	143111480	Needle sleeve	15
9	1	320054080	Friction bearing	16
10	1	143111450	Ball bearing, 17x35x10	20
11	1	343441380	Plate	15
12	2	141123720	Fillister head screw	11
13	1	141180110	Retaining ring	12
14	1	344000330	Sealing ring	14
15	1	330006990	Baffle	21
16	1	343441320	Motor cap	30
17	1	310011740	ARMATURE	50
18	1	143111610	Ball bearing, 7x19x6	24
19	1	143111120	Ball bearing, 10x26x8	25
20	1	343441300	Motor housing	34
21	1	343441390	Motor Air Guide Sleeve	23
22	1	310011700	Stator	37
23	1	344530220	Strand	16
24	2	344530230	Strand	14
25	1	344530240	Strand	14
26	2	141118970	Self-tap. fill. h. screw	11
27	1	341006330	Sleeve	15
28	1	344113250	Rubber bushing	14
29	1	343410850	Electronic switch 230V	38
30	1	344488530	Cable with plug	28
31	1	344113270	Cable sleeve	17
32	1	343441920	Holder	15
33	1	343050310	Terminal	19
34	1	343441360	trigger-sealing	18
35	1	343013300	Carbon brush set	32
37	22	141123760	Fillister head screw	11
38	4	141123790	Fillister head screw	11
39	2	141121960	Self-tap. fill. h. screw	11
40	1	343441940	CABLE CLAMP	14
41	1	343441430	Cover	15
42	2	343441930	Pressure plate	14

Позиция	Количество	Номер для заказа	Описание	PG
43	1	316092690	Handle half compl.	25
44	1	343441290	Buffer	25
76	1	338064670	Rating plate,14044XX0, RWE 1020	11
77	1	338122370	M-Label,56x25	12
1001	1	338510040	Wiring diagram	